

USA SCT Barrel Module Assembly

SCT Week CERN
March 2004


Presented by Abe Seiden
U.C. Santa Cruz

Hybrid Production

- Strongly coupled to deliveries and reworks
- 407 (359) started (completed) total, 116 (131) since last SCT week.




Production Model




Shipping

- Shipping boxes and configuration adopted.
- Test shipment of 9 mechanical modules sent to RAL complete.
- No visual damage.
- Metrology done on 2, UK & USA agree.
- Mechanical shock loggers not set properly so no feedback, test underway on return shipment
- Digital shock logger needs to be specified by SCT
- Expect first real shipment of 20 in ~1 week

Metrology: Midyf history




Midxf (10 μm)





Stereo Angle (130 mrad)

Stereo




Sepf and Sepb (10 μm)




Hole



Mhx



Mhy




Slot




Leakage Current of 4 Wafers


I in microamps @ 500V at about 20C



Bad Channels per Module



Module Yields - Classified



Module Categories

	378	ATLAS Classified
69%	260	ATLAS Good
80%	303	ATLAS Good+Pass
94%	355	ATLAS Good+Pass+Hold
96%	362	ATLAS Good+Pass+Hold+Rework

Hold Categories – 61

- Hold spreadsheet prepared and submitted
- Metrology: 26 with parameters outside PASS, most are due to small deviations
- Leakage current : 9 which don't condition, 3 which are on the margin
- Leakage glue: 10
 - 3 only in gap
 - 2 with minimal glue onto surface
 - 5 with glue on surface but not on pads
 - Most of these occurred early, rate now is ~once every hundred modules. May be due to shim round-off error.
- Other: ~9 have slight mechanical damage on PA or on edge of silicon, most otherwise perform well.


Position on HOLDS/FAILS

- On spreadsheet have indicated USA assessment of most HOLD and FAIL
- Would like those which pass to enter the workflow now so they can be absorbed gradually.
- Position
 - Most mechanicals out of spec should be used.
 - Parts with glue in crack or on surface but not on pads should be used.
 - Parts with slight mechanical damage but good IV should be judged now by module community (see pictures)


Examples of damage: these SB have good IV curves



Minimal glue leakage



Larger area glue leakage



Edge chip damage



Corner chip damage

Fail and Rework Categories

- Metrology: 2
 - Completely off due to wrong DIMS file
 - Vacuum failure during cure
- Broken or damaged: 4
 - Accidents
- Reworks: 7
 - 3 are hybrids too high
 - Have fixed one so far with hot wire to cut glue under foot
 - Expect to repair others eventually
 - 4 are bond damage or dirty
 - Expect to repair with some add'n bad channel or leakage